CONGAREE MR11 WELL LIGHT




DESCRIPTION

The Congaree Well Light is fitted for any MR11 lamp. The flat glass top comes in a brass finish.

CONGAREE WELL LIGHT

Use	Well Lighting & Underground Up Lighting Brass, Copper, or Brass w/ Black Cerakote®	
Finish		
Includes	LightingShrink Professional Crimp and Heat Shrink Cable Connector	
Warranty	Lifetime Warranty on National Parks Series Fixtures	
Order With	MR11, 2W, 2700K, 30°	CONGAREE-MR11-BR
Lamp		CONGAREE-MR11-CU
		CONGAREE-MR11-BR-BLK
Order Without	Fits MR11	CONGAREE-MR11-BR-NL
Lamp		CONGAREE-MR11-CU-NL
		CONGAREE-MR11-BR-BLK-NL












Brass (BR)

Copper (CU)

Brass + Black Cerakote® (BR-BLK)





CONGAREE-MR11-BR

INSTALLING THE LAMP

- 1. Remove the rear cap and pull out the spring.
- 2. Set the MR11 lamp on top of the spring and plug it into the socket.
- 3. Insert this assembly into the fixture body with the front of the lamp toward the lens.
- 4. Screw the back cap onto the fixture body and hand tighten.

INSTALLING THE FIXTURE

- 1. Dig a hole in the ground approximately 8" wide by 10" deep.
- 2. Connect the power cable to the fixture, leaving 2 feet of wire coiled in the bottom of the fixture for future service.
- 3. Pour 5" of pea gravel in the hole.
- 4. Place the fixture in the center of the hole.
- 5. Add more pea gravel to fill the hole 1" before the fixture lip. This allows for proper drainage around the fixture.
- 6. Apply glass wax on top of the lens to protect against standing water.